



Model Number: 9500VR

J.E. Adams 9500VR, Vacuum and Shampoo/Spot Remover, With Bill Acceptor, Vault Ready Combination Unit

Manufacturer: J.E. Adams

Combination Unit  
Car Wash and Auto Detailing

#### Features:

Two-timer digital display with built-in coin counter, scrolls messages, price for service depending on toggle switch setting, counts down time, and recalculates time if switch is toggled in mid-cycle with last coin lamp and alarm

Mars Series 2000 bill acceptor takes \$1.00, \$2.00, and \$5.00 bills (Item #8130-6)

Imonex electronic coin acceptor takes U.S. \$1.00 coins, U.S. quarters, 1.073 and 0.984 tokens

(Item #8149-92)

Double service doors offer easy access to clean out compartment and 4 filter bag system (Item #8076)

Toggle switch on faceplate to select vacuum or shampoo/spot remover

Rocker switch on brush to select shampoo or spot remover

Thomas 1/12 HP oil-less air compressor (Item #8824)

Twin cam lock for faceplate and shampoo/spot remover formula compartment

Lighted dome available in red, blue, yellow, dark green, light green, purple, and white

Comes with 1 gallon each of J.E. Adams's premixed formulas: shampoo and spot remover

Dispenses 2.5 gallons of foam per minute, 2 oz. of shampoo or spot remover makes 5 gallons of foam

Hose: 2" x 15', swivel cuff and nozzle included (15', 25', and 50'; available in 1 1/2" or 2")

Optional coin mechs, motors, colored hoses, extra security, and clean-out container are available.

[Print Brochure](#)

[Print Manual](#)

[Print Fragrance Data Sheet](#)

[Print Shampoo Data Sheet](#)

[Print Spot Remover Data Sheet](#)

Category:  
Car Wash

Line:  
Combination Units

Model #:  
9500VR

Shipping Weight:  
232.00 lb.

#### Description:

This unit comes standard with the following features (unless noted) and identifies replacement products:

- (2) 1.6 HP, 120 volt motors (Replacement Item #8055EM)
- Requires 20 AMP service
- Thomas 1/12 HP oil-less air compressor (Replacement Item #8824)
- 4 quick-change filter bags (Replacement Item #8076)
- Mars series 2000 bill acceptor takes \$1.00, \$2.00, and \$5.00 bills (Replacement Item #8130-6)
- Twin cam lock locking system used for faceplate (Replacement Item #8953)
- Pin lock style locking system for coin box (Replacement Item #8638)
- 2 service doors for easy maintenance
- Toggle switch to select vacuum or shampoo/spot remover
- Rocker switch on brush to select shampoo or spot remover
- Two-timer digital display with built-in coin counter, scrolls messages, price for service depending on toggle switch setting, counts down time, and recalculates time if switch is toggled in mid-cycle
- Last coin lamp and alarm
- Imonex electronic coin acceptor takes US \$1.00 coins, US quarters, 1.073 and 0.984 tokens (Replacement Item #8149-92)
- Hoses: Black, 15' and 50'; swivel cuff and nozzle included (25' and 50' also available in 1 1/2" or 2" for additional charge).
- 2" x 15' hose available in red, blue, yellow, green, and beige at no additional charge
- Lighted dome available in red, blue, yellow, dark green, light green, purple, and white
- Optional Service Door Security Door Item #9427K available at an additional fee.

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

- Optional Clean-out Bag (Item #8599) and Clean-out Container (Item #8080) are available for purchase
- Comes with 1 gallon each of J.E. Adams's premixed formulas: (1) shampoo and (1) spot remover

• Shampoo & Spot Remover dispenses 2.5 gallons of foam per minute, which is equal to 1 oz of liquid formula. 1 gallon of liquid formula = 128 oz and the dispensing rate is 1 oz per minute. One gallon of liquid formula yields 128 minutes of vend time.

VAULT READY DESCRIPTION: There are two primary ways to store coins in a self-serve environment; either inside the equipment in a coin box or in a vault that is installed beneath the meter to collect coins. Vaults can hold anywhere from \$700 in quarters for the 10-inch model up to \$1600 for the 18-inch (10" and 14" and 18" vaults available for sale). Since most vaults are cemented or bricked in on all sides they are very difficult for thieves to break into.

Also marketed as Part VAA9500

Availability: This product was added to our catalog on Friday 20 May, 2011