

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

0011	30410-206	**BRG,ROLL CYL	1	EA
0012	30275-6206	**BRG,BALL 1 ROW	1	EA
0013	30298-5206	**BRG,BALL 2 ROW	2	EA
0022	42005384	RETAINER BRG 400542	EA	
0023	42005384	SEAL LIP W/VITON	1	EA
0024	42005388	SEAL LIP W/VITON	4	EA
0029	90293-100	-SCREW,CAP SOO HD 3/8	2	EA
0030	42003088-003	SHIM- TIMING	6	EA
0030	42003088-005	SHIM- TIMING	2	EA
0030	42003088-010	SHIM- TIMING	2	EA
0031	42003188	KEY,gear TIMING	2	EA

Model Number: 12185
Tuthill 12185 Nitrile Lip Seal blower Repair Each

Manufacturer: Tuthill

Tuthill 12185 Nitrile Lip Seal blower Repair Each

Please allow 7 to 14 days for production

Sorry above thumb nail photo is not correct representation of the part.

Tuthill Blower Brochure

Availability: This product was added to our catalog on Wednesday 19 June, 2013