

MODEL 4002, 4005, 4007 COMPETITOR® PLUS™ (2-lobe)

The following list are recommended spare parts for a normal overhaul.
This list includes all bearings, seals, and miscellaneous locks and screws
that are not normally reusable after disassembly.

Item Number	Description	Part Number	Quantity
11	Roller Bearing	29251	1
12	Ball Bearing	11783	1
13	Ball Bearing	30238-5206	2
22	Retainer	4200538A	1
23	Lip Seal	4200548A	1
24	Lip Seal	4200558B	4
29	Cap Screw	90293-100	2
30	Timing Shim	4200308B-010	2
30	Timing Shim	4200308B-005	2
30	Timing Shim	4200308B-003	6
31	Gear Key	4200318B	2

Model Number: 4200548A

Tuthill 4200548A Repair Lip Seal (Only) Around Shaft Viton MODEL 4002 4005 4007 Competitor Plus (2-lobe)

Manufacturer: Tuthill

MODEL 4002, 4005, 4007 COMPETITOR ® PLUS™ (2-lobe)

A purchase from this web page is only for the Lip Seal kit and nothing else!

The following list are recommended spare parts for a normal overhaul.
This list includes all bearings, seals, and miscellaneous locks and screws
that are not normally reusable after disassembly.
Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$125 (thumbnail
image shows \$50 and that is wrong!)

Item Number	Description	Part Number	Quantity
11	Roller Bearing	29251	1
12	Ball Bearing	11783	1
13	Ball Bearing	30238-5206	2
22	Retainer	4200538A	1
23	Lip Seal	4200548A	1
24	Lip Seal	4200558B	4
29	Cap Screw	90293-100	2
30	Timing Shim	4200308B-010	2
30	Timing Shim	4200308B-005	2
30	Timing Shim	4200308B-003	6
31	Gear Key	4200318B	2

The following part is listed for reference only and is not a part of the repair kit:

8 Gear Assembly 4200098B 1

A purchase from this web page is only for the Lip Seal kit and nothing else!

Tuthill Blower Brochure

OPTIONAL

Important Option

Oil level must be topped off on new blowers
Oil level must be changed after 50 hour break in period.
Oil level must be changed every 200 hours after break in period.
Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula
Extra Heavy Duty for High Heat Applications 28G47-QT

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

Add to your shopping cart now!

Tuthill 4500638B Full Repair Kit for MODEL 4002, 4005, 4007
COMPETITOR PLUS (2 and 3 lobe all versions)

Availability: This product was added to our catalog on Friday 22 August, 2014