



Model Number: 601-002-701

HydraMaster 601-002-701 CDS 4.8 Truck Mount Vacuum Blower Dual Shaft Complete Blower Assembly

Manufacturer: HydraMaster

ALL HYDRAMASTER ORDERS ARE FINAL, NON-CANCELLABLE, NO REFUNDS, PRICES SUBJECT TO CHANGE BASED ON DATE SHIPPED!

HydraMaster CDS 4.8 VACUUM BLOWER TWIN SHAFT Replacement Pump



Used on: Hydramaster CDS 4.8 and Zerorez EWS Clutch Drive System.

Dual splash lubrication.

Dual drive Shaft

Part number represent the complete assembly of parts. Not just the vacuum blower but everything seen here.

If you only want to purchase the vacuum pump, visit part number on this website 000-111-147

Important Option

Oil level must be topped off on new blowers

Oil level must be changed after 50 hour break in period.

Oil level must be changed every 200 hours after break in period.

Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula

Extra Heavy Duty for High Heat Applications 28G47-QT

Add to your shopping cart now!

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

PHY111-006

Availability: This product was added to our catalog on Friday 18 May, 2018