



Model Number: 08-00257

Drieaz 08-00257, Replacement Blower Motor Fan Assembly 102564, Dri-Eaz Drizair 1200 Dehumidifier F203 4 wire version

Manufacturer: Drieaz

Drieaz 08-00257 Replacement Blower Motor and Fan Assembly 102564 for a Dri-Eaz Drizair 1200 Dehumidifier F203

#### Description

Blower assembly for the Dri-Eaz Drizair 1200 dehumidifier F203.

#### Specification

115v

60Hz

1.76A

1550 RPM

Thermally Protected

Class B

Item 08-00257 was replaced by item 102564 (3 wire version)

Item 102564 was replaced by item 122846 (4 wire version)

Read repair press release [HERE](#)

#### Pictures

Availability: This product was added to our catalog on Tuesday 27 August, 2019