

MODEL 4002, 4005, 4007 COMPETITOR® PLUS™ (2-lobe)

The following list are recommended spare parts for a normal overhaul.
This list includes all bearings, seals, and miscellaneous locks and screws
that are not normally receivable after disassembly.

Prices quoted are Ex Works, Springfield, MC, USA. Minimum order \$50.

| REPAIR KIT 4500638B | | | |
|---------------------|----------------|--------------|----------|
| Item Number | Description | Part Number | Quantity |
| 11 | Roller Bearing | 292011 | 1 |
| 12 | Ball Bearing | 117183 | 1 |
| 13 | Ball Bearing | 30238-5206 | 2 |
| 22 | Plunger | 42003584 | 1 |
| 23 | Lip Seal | 4200548A | 1 |
| 24 | Lip Seal | 4200558B | 4 |
| 28 | Cap Screw | 80203-100 | 2 |
| 29 | Timing Shim | 4200308B-010 | 2 |
| 30 | Timing Shim | 4200308B-005 | 2 |
| 30 | Timing Shim | 4200308B-003 | 6 |
| 31 | Gear Key | 4200318B | 2 |

Model Number: 5600638F

Tuthill 5600638F Repair Kit for Tuthill Blower model 500622L3N-C001

Manufacturer: Tuthill

Tuthill 5600638F Repair Kit for Tuthill Blower model 500622L3N-C001

Please order each!

Thumbnail image is not correct. We do not have a photo of this item or exactly what it includes.

Tuthill Blower Brochure

Important Option

Oil level must be topped off on new blowers

Oil level must be changed after 50 hour break in period.

Oil level must be changed every 200 hours after break in period.

Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula

Extra Heavy Duty for High Heat Applications 28G47-QT

Add to your shopping cart now!

Availability: This product was added to our catalog on Thursday 06 January, 2022