



Model Number: 3300638C

Tuthill 3300638C Repair Kit for Model 3003-A6L2CV1-A

Manufacturer: Tuthill

KIT CONSISTS OF BEARING, ROLL CYLINDER PART

BEARING, BALL, 1 ROW PART

2 BEARING, BALL, 2 ROW PART

2 RETAINER PART

1 SEAL, LIPW VITON PART

4 SEAL, LIP W VITON PART

2 SCREW, CAP, SOCKET HEAD PART,

6 SHIM, TIMING PART

2 SHIM, TIMING PART

2 SHIM, TIMING PART

AND 2 KEY, GEAR TIMING PART

Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$50.
Tuthill Blower Brochure

Important Option

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

Oil level must be topped off on new blowers
Oil level must be changed after 50 hour break in period.
Oil level must be changed every 200 hours after break in period.
Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula
Extra Heavy Duty for High Heat Applications 28G47-QT
Add to your shopping cart now!

Availability: This product was added to our catalog on Tuesday 23 August, 2022