


Equipment: [Carpet Cleaning Machines](#) > [Vacuum Cleaners](#) > [HEPA Concrete Dust Slurry Hazmat Vacuums](#) >



Model Number: 200-120

Clean Storm 2000 watt Internal Heater Repair (Large style) 200-120 Sandia 80-8001

Manufacturer: Clean Storm

Replacement 2000 watt Heater repairs Mytee Old 200-120 Heaters and Clean Storm 2000 watt heaters

Single large Stainless Steel Core, dual 1000 watt heating systems.

Includes: Core, dual 1000 watt rods, 4 thermostats, insulation, and wrap.

Fits inside:

and

and currently used the following brands of carpet cleaning extractors: Sandia Plastic, Clean Storm...

---

Availability: This product was added to our catalog on Tuesday 09 October, 2012