

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

Steambrite Supply

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >



Model Number: 150150

AH50 1.5in Threaded X 1.5in Threaded Vacuum Hose Cuff 1606-0980 (Double threaded) [150150]

Manufacturer: Clean Storm

AH50 1.5" Threaded X 1.5" Threaded Vacuum Hose Cuff and repair kit

Please note that the inside diameter of this cuff is about 2." because it screw over the outside of 1.5" inside diameter carpet cleaning vacuum hose.
The wall thickness on vacuum hose is over 1/4" thick so you have 2" measuring across the inside of this joiner.

This is a type of vacuum hose connection is great for live hose reels used with truckmounted vacuum cleaning machines because these offer less vacuum inside hose turbulence than traditional barbed hose insert connections.

Can also be used to fix and repair cracked 1.5" ID vacuum hose for swimming pool hose and carpet cleaning hose.
Simply cut all the way through the crack and screw on both sides.
Optional glue could be installed for a more permanent connection.

Compare to current or past OEM associations:

AH50
1606-0980
150150
SBM150150
108096
150-150VC-GY

Availability: This product was added to our catalog on Tuesday 18 March, 2014