

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

Steambrite Supply

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >



Model Number: 20140530

San Antonio Plastic Welding and Tank Repair 1 Hour min charge collected up front for testing

Manufacturer: San Antonio Equipment Repair

Plastic Tank Repair and Plastic Welding in San Antonio, TX

These photos are an example of a split water tank that was fixed by plastic welding, siliconing, and using special water tight rivets with aluminum bracket.

Cost of service \$100 per hour + parts and sales tax.

Optional pickup and delivery \$37.50 + \$1.2 per mile round trip.

1 hour min charge collected up front for testing.

18975 Marbach Ln #200-C

San Antonio, TX 78266

When dropping off and picking up your equipment:

Steambrite is not responsible for theft or damage to your property while it is at our facility undergoing repairs or while being stored and awaiting pickup. Steambrite employees will gladly assist in the unloading and loading of your merchandise, but are not responsible for any damage that might occur to your equipment or vehicle. It is the customer responsibility to confirm there equipment is loaded and secured properly for transportation. LIMITATION OF DAMAGES: THE REMEDY OF REPLACEMENT OR REPAIR OF ANY DEFECTIVE GOODS SHALL BE EXCLUSIVE. IN NO EVENT SHALL STEAMBRITE BE LIABLE FOR ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES PROPERTY DAMAGES, OR PERSONAL INJURIES.

Availability: This product was added to our catalog on Friday 30 May, 2014