

[Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >](#)



Model Number: PRT50700

Clean Storm 875 Watt Rod Style Heating Element Heater repair 115 volt PRT50700 10-1500-C

Manufacturer: Clean Storm

Replacement heater rod for most brands of carpet cleaning machines.

Rod is 1/2" thick and 7-1/8" long (without wire leads included in the measurement)
Wire leads are permanently attached.

This requires that the solderless connections be replaced.

Please note: it is NOT OK to use 12 volt rated automotive connectors made out of vinyl.

You must use nylon connectors instead rated for 120 volts.

Using the wrong connections can cause your machine to catch on fire!

Fully Nylon-Insulated Female EZ Disconnect 14-16 AWG each 4X299-1
BLUE Solderless Connector 1/4in Wide

Availability: This product was added to our catalog on Friday 29 May, 2009