



Model Number: FP159

US Products Heat Exchanger 120 volt for Extractor HHP-300 FP159 Alternative

Manufacturer: US Products

Use this NEW heater to either add heat to your non heated carpet cleaning machine or fix or repair your complete heating assembly in your US Product HHP-300 extractor.

Heater consumes 16 amps of power and needs a dedicated 20 amp breaker.

Part number FP159

Photo is not accurate and only a representation of what it could look like.

**2018, March factory discontinued supporting this item, please visit

Clean Storm Heat Exchanger 120 volt for Complete Heat Goliath 1700 watts
20150925

NOTE: This heater has 1/4" male pipe welded on both the water in and out so you will have to purchase some brass parts to convert to fit a US Products machine.

March 2018 Factory states they and special order this item with a 3 week wait.


US Products Heat Exchanger 120 volt for Extractor HHP-310 FP159H

We have no way of knowing what the difference is between FP159 and FP159H so I am sure you might have to purchase some type of bushing or fitting to make it fit for your machine!

Prochem Century 400 Ninja Warrior Windsor Dominator Diamondback
Replacement Heater Assembly 1850 watts 115 volts 8.602-794.0 8.603-590.0
Esteam 490-005

NOT TECH SUPPORT AVAILABLE FOR THIS PART. YOU WILL HAVE TO FIGURE OUT HOW TO MAKE THIS FIT/WORK FOR YOUR MACHINE.

Equipment: [Carpet Cleaning Machines](#) > [Vacuum Cleaners](#) > [HEPA Concrete Dust Slurry Hazmat Vacuums](#) >



Availability: This product was added to our catalog on Thursday 12 February, 2015

Steambrite Supply