



Model Number: F503

Drieaz F503 and Sapphire 20-045 Filter 4 Pack 105626 - for the HVE3000 Water Extraction Machine

Manufacturer: Drieaz

Drieaz F503 and Sapphire 20-045 Filter 4 Pack for the HVE3000 Water Extraction Machine

Note: To help prevent cross-contamination, we recommend replacing the HEPA filter after each job involving mold, sewage, or other microbial contaminants, and also after use in an environment that may contain toxic substances such as asbestos. Wear appropriate protective gear when handling contaminated filters and dispose according to local regulations.

It states in the manual:

Replace HEPA filter. Replace when the filter is visibly dirty. To access the filter, remove the filter cover plate thumbscrews and lift off the plate. Replacement filters are sold in packs of four. Ask for Dri-Eaz part no. F503 or Sapphire part no. 20-045.

HEPA Exhaust Filters for the HVE3000

Maintain HEPA filtration on your HVE3000 Flood Pumper

The HEPA filter on your HVE3000 Flood Pumper helps to capture extremely fine particulates before they are recirculated into the jobsite. Change the filter often to ensure the cleanest working environment for your technicians and for returning occupants.

What is happening is that the customers are not changing the HEPA filters which is overheating the vacuum blowers on the unit.

Availability: This product was added to our catalog on Monday 06 July, 2015