

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

Steambrite Supply

No image

Model Number: 3300638E

Tuthill 3000 Repair kit 3300638E

Manufacturer: Tuthill

The following list are recommended spare parts for a normal overhaul. This list includes all bearings, seals, and miscellaneous locks and screws that are not normally reusable after disassembly.

REPAIR KIT 3300638E

| Item Number | Description | Part Number | Quantity |
|-------------|------------------------|-------------|----------|
| 11 | Roller Bearing | 28680 | 1 |
| 12 | Ball Bearing | 8498 | 1 |
| 13 | Ball Bearing | 30238-5205 | 2 |
| 22 | Retainer | 3300538A | 2 |
| 23 | Lip Seal | 3300548B | 1 |
| 24 | Lip Seal | 3300558B | 4 |
| 29 | Cap Screw | 90293-100 | 3 |
| 30 | Timing Shim | 8550 | 2 |
| 30 | Timing Shim | 8533 | 6 |
| 30 | Timing Shim | 8532 | 2 |
| 31 | Gear Key | 3300318B | 2 |
| 44 | Roller Pin 1/8 x 13/16 | 93049-081 | 2 |
| 48 | Roller Pin 1/8 x 5/8 | 93049-062 | 1 |
| 50 | Lip Seal, Teflon | 3300408C | 4 |

The following part is listed for reference only and is not a part of the repair kit: 8 Gear Assembly 3300098B 1

20170607JMG

Availability: This product was added to our catalog on Wednesday 07 June, 2017