



Model Number: E41-5

CRB Cleaning Systems E41-5, 73 mm Gear With No Bearings, 5 Pack Repair kit, for CRB Floor Scrubber Machine TM4 and TM5

Manufacturer: CRB Cleaning Systems

CRB Cleaning Systems E41-5 73 mm Gear With No Bearings 5 Pack Repair kit for CRB Floor Scrubber Machine TM4 and TM5

Features

- 5 Pack of E41 gear
- Gear Teeth Right (From Left to Right)
- 73 MM gear with NO bearings.
- You will receive 5 gears of all the same size
- Position Upper Right Gear (See diagram below.)

Pictures

---

Availability: This product was added to our catalog on Monday 01 July, 2019