



Model Number: 20230715

Air Wave Duct Cleaning System, AC040 1682-2987 Dryer Vent cleaning, HEPA Vacuum Fogger Air Compressor Bundle 20230715

Manufacturer: Clean Storm

Air Wave Duct Cleaning System AC040 1682-2987 And Dryer Vent cleaning W 335Cfm HEPA Vacuum, ULV Fogger, 13 CFM Air Compressor, Sanitizer, Bundle 20230715

Bundle includes (click on each item to open in a new tab):

Air Wave Duct Cleaning System AC040 1682-2987 And Dryer Vent cleaning

Clean Storm HEPA Concrete Grinder Dust Slurry Extractor Collector Triple Vacuum Motors 5 Stage Filter System Wet/Dry Shop Vac 335CFM 20230111 - Video On Link!

BE Pressure AC658HB 8 Gallon Wheeled Gas Compressor 13.8cfm 90psi 196cc Honda Engine

FGI SMITH ULV Cold Disinfectant Fogger / Mister 115 volts K9-2600
[AS40] 190444 190695W

Sporicidin Disinfectant RE-1284F 4/1 Gallon CASE CH1286 861105
Sodium Phenate / Phenol

Pictures

Video

Duct Cleaning System

Whether you are starting up a new duct cleaning business, adding duct cleaning to your already existing carpet cleaning business, or upgrading your current system, the Air Wave Duct Cleaner is the most effective and cost efficient duct cleaning solution on the market.

According to the EPA a thorough duct cleaning job; which includes cleaning of the ducts, grills and air handler, runs from \$450 - 1,000 so you'll be able to completely pay for the Air Wave Duct Cleaner in as little as 2 jobs! Cleaners that concentrate on duct cleaning as a service are able to add up to \$100,000 in additional income each year.

Heating and cooling systems can become inefficient do to dust buildup and potentially exacerbate health conditions such as asthma and allergies. Ducts can be filled with construction materials, mold, dust and pollens. Homeowners can use duct cleaning to

lower electric and gas bills and keep their living spaces clean. 9 out of 10 system failures are caused by dirt and dust according to the Louisiana Cooperative Extension Service. One of the functions of the fan, located inside of your air handler, is to keep the heat exchanger cool. Accumulated dirt and debris can reduce the CFM (cubic feet of air per minute) by as much as 50%! This is the most common cause of cracks in heat exchangers. Having your HVAC system cleaned may prevent pre-mature breakdown & aging of your heating and cooling system. The EPA states that a buildup of only .042 inches of dirt on a heating coil can result in a decrease of efficiency of 21%. A clean air conveyance system will keep an HVAC system running efficiently and reduce heating and cooling costs.

Cleaning dryer vents is another service that can be done with duct cleaning equipment. Clogged dryer vents represent a serious fire hazard. As the dryer vent becomes occluded with very combustible lint, it decreases the dryer's efficiency and can increase the heat in the vent to the point of actually causing the lint to ignite.

Included Items:

- Vacuum Box Assembly #AC041
- 2" Male Flash Cuff with Male NPT and Lock Nut #AH224 and #NM6102
- 2" Female Flash Cuff #AH204
- 2" to 1.5" Female Reducer Flash Cuff #AH201
- LED Light #AC043
- Toe Kick Adapter Plate #AC042
- 25' Cleaning Air Hose #AH040
- 50' Compressor Air Hose #AC031A
- Black Pusher Ball #NM6109
- White Reverse Blaster Ball #NM6108
- Extension Pole #AC049 and Pole Ball End #NM6110
- Air Gun #AC047
- Air Shutoff Valve #AH54
- Male Air QC $\frac{1}{4}$ " FPT #PAF17, $\frac{1}{4}$ " MPT #PAF18, Female Air QC #PAF19
- Air Wave Carry Bag #AC046

Compare to current or past OEM associations

673516071

AC040

1682-2987

122034

Optional

Clean Storm 20230809 Air Duct Cleaners Basic 60 Gallon Air Compressor Starter Bundle 13.1 CFM Dual 120 Volts 16 Amps
No gasoline needed.

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >

-->

Availability: This product was added to our catalog on Thursday 13 July, 2023